

## Old Church windows

Many of you will remember an earlier article about the stained glass in the chancel of the Old Church. After a long wait the repairs to the damaged glass have been completed by Chapel Studio and the glass has been replaced. A careful repair had to be done to an area of glass in the window that has the arms of Eton College, where there were cracks. The glass has been laminated to hold it together. The before and after pictures show what has been done.



More obviously perhaps, the mesh guards that protect the glass have been replaced with much more discreet ones that enhance the exterior appearance of the church and also reveal aspects of the construction of the window surrounds that were otherwise obscured.



**Peter Hounsell**